

# Report of Survey for Repairs, &c., of Engines and Boilers.

SAT 15 JUN 1895

(Received at London Office)

Port of London

Date of writing Report June 14<sup>th</sup> 1895 When handed in at Local Office

No. in Reg. Book. 297 Survey held at London

Date, First Survey June 4<sup>th</sup> Last Survey June 14<sup>th</sup> 1895

on the Machinery of the Wood, Iron or Steel S.S. Cassel

Master G. Grant

Tonnage Gross 448  
Net 257

Vessel built at Amthampton By whom Amthampton & Walsby When 1891

Registered Horse Power 95

Engines made at Do When 1891 Boilers, when made (Main) 1891 (Donkey) 1891

No. of Main Boilers 1

Owners Meadson & Huxley Port London Voyage Dunkirk

No. of Donkey Boilers 1

Steam Pressure in Main Boilers 160

If Surveyed Afloat or in Dry Dock Given

in Donkey Boilers 30

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A.I. 11.94		+LMC 4.91

Last Survey No. 56577 Port Lon

Particulars of Examination and Repairs (if any) Completion of Special Survey

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Excd in May last

Do. " Donkey " " " Yes

If this was not done, state for what reasons? "

And what parts of the Boilers could not be thus thoroughly examined? "

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? "

Did the Surveyor examine the Safety Valves of the Main Boiler? Excd in May last

At what pressure were they afterwards adjusted under steam? 160 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes

To what pressure were they afterwards adjusted? 80 lbs

If the Survey is not complete state what arrangements have been made for its completion? "

Donkey boiler opened out cleaned and examined all parts found in good order Safety valve examined and adjusted under steam to the above pressure

Main safety valve adjusted under steam to the above pressure

The above completes the special survey on the machinery of this vessel, for previous survey see London Report No 56577

General Observations, Opinion, and Recommendation: In my opinion the machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 1,01, B.&M.S. 1,01 or L.M.C. 1,01, 140 lb., F.D., &c.)

of this vessel is now in good order and safe working condition and eligible for the notification +LMC 5.95 in the Register Book

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	Received by me,
				18

Geo A Milner  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required


Committee's Minute TUES 18 JUN 1895

Assigned +LMC 5.95

MACHINERY  
WRITTEN.

TUES 25 JUN 1895

© 2019



Lloyd's Register  
Foundation

State if a Report is also now sent on the Ship.  
\* If not whether, and when, one will be sent.

\*Certificate to be sent to  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

16-LRPH-Report No. 9-Transfer Ink-5,000, 3/4, 03

Insert Character of Ship and Machinery precisely as in the Register Book.



N.º 1 due 4.95 pt. held on well

It is submitted that  
this vessel is eligible for  
THE RECORD: + LMC 5,95

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

A P R  
17.6.95

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation