

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of London
No. in Reg. Book. Survey held at London Date, First Survey 20th June Last Survey 21st June 1895
(No. of Visits) Master Henry

172 on the ~~Wood, Iron or Steel~~ Plk "Harold"
TONNAGE:— Built at Plk Glasgow By whom R. Duncan & Co When 1888 - 5
GROSS 1376 Owners J. Stephens & Sons Port belonging to London
UNDER DE 1162 Owners' Address
NET 1299 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock London Graving Dock Destined Voyage ✓
WB=Cell DBorDBa tons; uE&B tons; f tons; }
FPT tons; APT tons; MT tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 41078 Port Lw
CHARACTER. *100A1
Date of Special Survey, 7.94
Date of last Survey and of Periodical Surveys. S.S. Sub No 1.93
Machinery and Boiler Surveys (including date of N.B., if any).

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition
Vessel placed in dry dock, bottom cleaned, examined found in good condition and re-coated with paint

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Other Items :—
Renewed		✓	✓	✓	✓	✓	✓
Faired or Repaired ...		✓	✓	✓	✓	✓	✓
PRESENT CONDITION OF THE		Timber of Frame at the openings		Rudder	Hatches		
Decks	Good	Ditto ditto at other places	"	Windlass & Capstan	Boats		
Stairways	"	Keelsons	"	Pumps	Masts, Yards, &c.		
Jeannings	"	Champs, Shells & Stringers	"	Sluice Valves	Condition, how ascertained		
Upper Dk. Beams & Fastenings	"	Salting	—	Watertight Doors	(State if wedges removed)		
Lower Dk. Beams & Fastenings	"	(State if examined.)	"	Dblng. Plates under Sounding Pipes	Sails		
Listing	"	Ceiling	"	Engine-Room Skylights	Equipment letter		
Planking	—	Cement or Plaster	"	Coal-Bunker, Open'gs, Lids, &c.	Anchors, No. of		
Transoms or Rivets	"	(State if on Felt.)	none	Souppers	Cables (State if now ranged)		
Breasthooks & Stanchion	"	Caulking of Bot'm, D'k, & Wat'rw'ys	"	Cargo & Main H'tch'w'ys	" length		
Transoms, Rotators, & Crotchets	"	Copper, or Y.M.	—		" Rule length		
		(State if on Felt.)	Year		Hawsers & Warps		
		When put on, Month			Standing & Running Rigging		

General Observations, Opinion as to Class, Recommendation, &c. :—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."
This vessel as far as seen is now in a good and efficient condition and eligible in our opinion to remain as classed, with record of survey 6.95 Lon in the Register Book

Office Fee (if chargeable) per Scale II, Sec. 27	£	Fees applied for,	18.
Survey Fee (per Section 25)	£	Received by me,	18.
Special Damage or Repair Fee (if any) (per Sec. 25.)	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
Character assigned 100A1
TUES 25 JUN 1895
Surveyor to Lloyd's Register of British & Foreign Shipping.
Lloyd's Register Foundation
LON705-0412