

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office WED. JAN 1 1896)

Date of writing Report *28th Dec 1895* When handed in at Local Office *30th Dec 1895* Port of *London*
No. in Reg. Book. *89* Survey held at *London* Date, First Survey *27 Dec 1895* and Last Survey *27 Dec 1895*
on the Machinery of the *Wood, Iron or Steel* *S.S. Warwick Castle* Master *J. Crisp*
Tonnage { Gross *3056* Net *1880* Vessel built at *Glasgow* By whom *A. Napier & Son* When *1877* 8
Registered Horse Power *435* Engines made at *Donkey* Boilers, when made (Main) *91* (Donkey) *91*
No. of Main Boilers *2* Owners *D. Currie & Co* Port *London* Voyage *of Good Hope*
No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *in Green's Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Steam Pressure in Main Boilers *160 lb* in Donkey Boilers *85*

Last Survey No. *56930* Port *London*
Particulars of Examination and Repairs (if any) *Boilers not under Survey*
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)
CHARACTER for Special Survey. Date of Last Survey and of Periodical Surveys. Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).
100A 1 9 95 *L.M.C. 4 74*
SS F.M. 3. 14 90 *+ N.B. 12 91*
SS F.M. 1 95

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
Do. " Donkey " " "
If this was not done, state for what reasons?
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler?
At what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of Donkey Boiler?
To what pressure were they afterwards adjusted?
Has the propeller shaft been drawn and examined at this time? *Yes*
If the Survey is not complete state what arrangements have been made for its completion? *Survey complete.*

Now done: Propeller Stern-bush and all outside fastenings of sea connections examined and found satisfactory.

General Observations, Opinion, and Recommendation:—
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 494, B.&M.S. 494 or L.M.C. 494, 140 lb., F.D., &c.)
The Machinery of this vessel so far as now seen, is in good condition and, in my opinion, eligible to remain as classed without fresh record.

Office or Registration Fee (per Sec. 27)..... £ : : Fees applied for
Survey Fee (per Section 28)..... £ : : 18
Special Damage Fee (per Section 28)..... £ : :
Travelling Expenses (if chargeable)..... £ : :
Received by me, *D. Atchue*
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.
*State if Certificate is required
Committee's Minute *FRI. JAN 3 1896*
Assigned *As now*

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

16-LRPH-Report No. 9-Transfer Ink-5,000, 3/4, 96.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

It is submitted that
this vessel is eligible to
remain AS CLASSED,

H.V.

2.1.96.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation