

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18... When handed in at Local Office 18... Port of London

No. in Reg. Book. Survey held at London Date, First Survey 7 Last Survey Sept 1896

35 on the Wood, Iron ~~on Steel~~ 3.9 "Galicia" (No. of Visits) Master J. A. Burton

TONNAGE: Built at Hartlepool By whom Denton, Gray & Co When 1866. 4

GROSS 756 Owners J. Hall jun: & Co Port belonging to London

UNDER DK 694 Owners' Address

NET 473 (if not already recorded in Appendix to Register Book.)

Surveyed ~~at~~ in Dry Dock? Name of Dock Lomekiln Destined Voyage Spain

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted

total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 57431 Port London

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Vessel dry docked bottom cleaned & recoated.

Rudder rebushed.

Is a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

Rpt. 8.—205.—5000.—21598.—Transfer Ink. The Surveyors are requested not to write on or below the space for Committee's Minute.

Is Certificate required? If so to be sent to



© 2020

Lloyd's Register Foundation

LON 710-0255