

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22-9-96 When handed in at Local Office 22-9-96 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 16-9-96 Last Survey 21-9-1896

1127 on the Wood, Iron or Steel s/s Cortes. Master Vinyo

TONNAGE:-

GROSS 1261

UNDER DK 1249

NET 951

Built at Sunderland

By whom Jas Laing

When 1882-7

Owners Cia maritima

Port belonging to Barcelona

Owners' Address

(if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock Regent Dry Dock Name of Dock Destined Voyage Spain for

WB=CellDBorDBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 56942 Port Lon

+100A.1. Sparke 18.9/95
with freeboard + huc 11/92

S.S. Lon 702-92

Society's Freeboard (if assigned) as painted on Ship and now verified

5 ft. 11 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition-

This steamer was placed in Regent Dry Dock the bottom examined cleaned & recoated. Notice was given to Mr Kennedy the Marine Supd Engineer that the Special Survey No 3 became due in July 1896 and was informed that the owners could not at the present moment detain the vessel for this survey but that she will be presented at an early opportunity next year, when she will be redocked for this inspection.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Faired or Repaired ...								
PRESENT CONDITION OF THE	Timbers of Frame at the openings.	Rudder	Hatches					
Decks	Ditto ditto at other places.	Windlass & Capstan	Boats					
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.					
Coamings	Stringers, Champs & Shells	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained					
Up'r Dk. Beams & Fastenings	Salting	Have Watertight Doors now been examined and found efficient?	(State if wedges removed)					
Low'r Dk. Beams & Fastenings	Ceiling	Dblg. Plates under Sounding Pipes	Sails					
Plating	Cement on Asphlt	Engine Room Skylights	Equipment letter					
Blanking	Tanks	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of					
Rivets on Trussing	Caulking of Bot'm, D'k, & Wat'rw'ys	Scuppers	Cables (State if now ranged)					
Breasthooks & Stems	Copper on Y.M.	Cargo & Main H'tch'w'ys	" length					
Transoms, Decks, & Crutches	When put on, Month		" rule length					
			(per Table 22)					
			Standing & Running Rigging					

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This steamer now appears to be in a sound and efficient condition eligible in my opinion to remain as classed without a fresh record of Survey

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,	£
Survey Fee (per Section 25)	£	Received by me,	£
Special Damage or Repair Fee (if any) (per Sec. 25.)	£		£
Travelling Expenses (if chargeable)	£		£
Second Surveyor's Fee (if any)	£		£

Committee's Minute

Character assigned

Deferred for No. 3.

Edward W. Turner

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUES 26 JAN 1897

FRI. 2 APR 1897

FRI. 17 JUN 1897

Lloyd's Register Foundation