

Lon 58534
58641

Mohawk

11. 29)
18. 3. 97

One indented plate temporarily repaired: to
be faired at first opportunity



© 2019

Lloyd's Register
Foundation

LON 712-0004.1