

Chain Bearing brasses (lower halves)

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

unnaltered & shafting lined up (due to
damage)

It is submitted that
this vessel is eligible to
remain as CLASSED.

HL
28/7/91

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation