

(Received at London Office 25.4.98.)

No. 59796A

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Reg. Book 211 Survey held at on the Wood, Iron or Steel Le. Tug Agnes Seed Date, First Survey Agnes Seed Last Survey
By whom Willoughby Bros. Master Young When 1892 MONTH 3

TONNAGE:— GROSS 93 Built at Ply Owners Y Seed
UNDER DK. 87 Owners' Address
NET 22 (if not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 43794 Port Dir
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys.
Year Assigned and expired.
Machinery and Boiler Surveys (including date of N.B., if any).
+ A1 + LMC, 10.95
For Tug purposes
8.96
S.S. Dir. No. 1-95
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.
BS due 3.98 SS No 2 due 3.98

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks	Ditto ditto at other places	Windlass & Capstan	Boats
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.
Coamings	Stringers, Clamps & Shelves	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained (State if wedges removed)
Up'r Dk. Beams & Fastenings	Salting (State if examined.)	Have Watertight Doors now been examined and found efficient?	Sails
Low'r Dk. Beams & Fastenings	Ceiling	Dbing. Plates under Sounding Pipes	Equipment letter
Plating	Cement or Asphalt (State which.)	Engine Room Skylights	Anchors, No. of
Planking	Tanks (State if now tested.)	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged) size (on board) size (per Table 22)
Rivets or Treennails	Caulking of Bot'm, D'k, & Wat'rw'ys	Scuppers	Hawsers & Warps
Breasthooks & Stemson	Copper, or Y.M. (State if on Felt.)	Cargo & Main H'tch'w'ys	Standing & Running Rigging
Transoms, Pointers, & Crutches	When put on, Month Year		

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and ptND97, &c."

Office Fee (if chargeable) per Scale II, Sec. 27	Survey Fee (per Section 28)	Special Damage or Repair Fee (if any) (per Sec. 28.)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,
£	£	£	£	£	18
					Received by me,
					18

Committee's Minute
Character assigned Withdraw class
insert
misc on 2.0 29/4/98
Surveyor to Lloyd's Register of British & Foreign Shipping.
General Comd 5th May, 1898
Decision of Classing Comtee
confirmed
LON 715-0217

If a Survey has been held on the Machinery of the vessel, the Report sent herewith should be accompanied by a separate Report on the Machinery, and if so, the Report sent herewith should be accompanied by a separate Report on the Machinery.

Is Certificate required? If so to be sent to