

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 4/6/98 When handed in at Local Office 4/6/98 Port of London
 No. of Survey held at London Date, First Survey May 24 Last Survey 28/5 1898
 on the Wood, Iron or Steel SS Portslade (No. of Visits) 4 Master Dickinson

TONNAGE:— Built at Sweden By whom R Thompson & Co When 1888—8
 GROSS 594 Owners S Clarke & Co Port belonging to London
 UNDER DECK 473 Owners' Address
 NET 336 (if not already reported in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Dugall Dock Destined Voyage Coasting
 WB=Cell DBor DBa feet; uE&B feet; I feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No.

Port Low 58796

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, + for Special Survey, Date of last Survey and of Periodical Surveys.
100741
597
5.5. no 2.97.

Society's Freeboard (if assigned) as painted on Ship and now verified } 1 ft. 6 ins.REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage

This steamer was reported to have taken the ground at Guernsey & bumped against the Quay wall on November 27-1897

This steamer was placed in dry dock, the bottom examined & cleaned & recoated
 one plate on the starboard side amidships just above bilge renewed. a butt strap fitted outside over defective butt in stoke above 6 frames & reverse frames faired in place

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	1	6	5	4	2	2	2	4
Removed and Faired or Repaired	—	—	—	—	—	—	—	—
Faired or Repaired in place	2	6	5	4	2	2	2	4

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks	Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Caulking of Decks	State if Tanks now tested	Scuppers	Condition, how ascertained
Waterways	Bulkheads	Cargo Hatchways	(State if wedges removed)
Coamings	Ceiling	Hatches	Sails
Beams & Fastenings	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter
Outside Plating	Rudder	Treenails ditto	313-15-2K
Caulking of ditto	Windlass	Breasthooks & Stemson ditto	Condition, how ascertained
Rivets	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length (on board) size
Transoms	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" full (on board) (per Table 22)
Frames		Stringers, Clamps & Shells ditto	Hawsers & Warps
Reverse Frames		Salting (State if examined.) ditto	Standing & Running Rigging
Floors		Copper, or I.M. (State if on felt.) ditto	
Keelsons	Dblg. Plates under Sounding Pipes	When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1998," or "to remain as classed and to have record of survey, 1998, and the notations of ss No. 1-98 and ptND98, &c."

This steamer now appears to be in good condition eligible in my opinion to remain as classed with a fresh record of Survey
Don 5/98

Office Fee (if chargeable) per Scale II, Sec. 47 £ : :
 Survey Fee (per Section 25) £ : :
 Special Damage or Repair Fee (if any) (per Sec. 25) £ : :
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :
 Fees applied for, 46 98
 Received by me, Edward J. Turner

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES. 7 JUN 1898

Character assigned

100A100A

© 2019

Lloyd's Register Foundation

LON715-0414