

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9/6.1898 When handed in at Local Office 15 Port of London  
No. in Reg. Book 206 Survey held at London Date, First Survey 7 Last Survey 4 June 1898  
(No. of Visits) Master A. Brettschneider

TONNAGE:-  
GROSS 887  
UNDER DECK 671  
NET 229  
Built at Middlesbrough By whom Baehner & Dixon When 1870 2  
Owners T. Rodenacker Esq. Port belonging to Danzig  
Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? at Name of Dock Fountain Quay Destined Voyage Danzig  
WB=Cell DBorDBa feet; uE&B feet; I feet;  
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59286 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
CHARACTER. \* for Special Survey. Date of last Survey and of Periodical Surveys. Year assigned and now expired. Machinery and Boiler Surveys (including date of N.B., if any).  
+ A. 1. 10-95  
5.97  
S.S. Don No 3-187 11/13/97  
S.S. Don No 2-95 13/15/97  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This vessel was placed on a gridiron, her bottom cleaned and recoated, but the vessel was afloat or nearly so at the time of my visit and no examination of bottom could be made. A few minor repairs to deck work were effected.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Good	Stringers	Good	Engine Room Skylights	Good	Boats	Good	
Caulking of Decks	do	Inner Bottom Plating	do	Coal Bunkers, Open'gs, Lids, &c.	do	Masts, Yards, &c.	do	
Waterways	do	State if Tanks now tested	do	Scuppers	do	Condition, how ascertained	From deck	
Coamings	do	Bulkheads	do	Cargo Hatchways	do	(State if wedges removed)	do	
Beams & Fastenings	do	Ceiling	do	Hatches	do	Sails	do	
Outside Plating	Above water do	Cement or Asphalt (State which.)	do	Planking of Wood Vessels	do	Equipment letter	do	
Caulking of ditto	do do	Rudder	Above water do	Treenails	ditto	Anchors, No. of	3B. 18. 1K.	
Rivets	do do	Windlass	do	Breasthooks & Stems	ditto	Cables (State if now ranged)	do	
Breasthooks & Crutches	do	Have Pumps now been examined and found efficient?	do	Transoms, Pointers, & Crutches	ditto	length (on board)	size	
Transoms	do	Have Sluice Valves now been examined and found efficient?	do	Timbers of Frame at openings	ditto	Rule length (per Table 22)	size	
Frames	do	Have Watertight Doors now been examined and found efficient?	do	Ditto ditto at other places	ditto	Hawsers & Warps	Good	
Revers. Frames	do	Salting (State if examined.)	do	Stringers, Clamps & Shells	ditto	Standing & Running Rigging	do	
Floors	do	Copper, or Y.M. (State if on Felt.)	do	Salting	ditto			
Keelsons	do	When put on, Month	Year	Copper, or Y.M. (State if on Felt.)	ditto			
		Dblng. Plates under Sounding Pipes	do					

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any, and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and pmd 98, &c."

This vessel, as far as seen, appears to be in a good and efficient condition and eligible in my opinion to remain as classed without fresh record of survey.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,	
Survey Fee (per Section 28)	£		18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,	
Travelling Expenses (if chargeable)	£		18
Second Surveyor's Fee (if any)	£		

Committee's Minute TUES. 14 JUN 1893  
Character assigned As now