

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28th June 1898 When handed in at Local Office 15

Port of London

No. in Reg. Book.

Survey held at London

Date, First Survey 23rd June Last Survey 24th June 1898

(No. of Visits)

Master

on the Wood, Iron or Steel 88 "Appomatox"

TONNAGE:-

GROSS 287.5

UNDER DECK 27.93

NET 18.21

Built at W. Hartlepool

By whom

Furness withy & Co

YEAR

MONTH

When 1893

9

Owners Chesapeake & Ohio S.S. Co.

Port belonging to W. Hartlepool

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock?

Name of Dock Victoria

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; I

feet; J

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Assigned
Surveyed
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).* 100A1
Spar Deck
7.97

* LMC 7.97

Last Report, No. 59854 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } 5 ft. 10 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Completion of S.S. No. 1

See Last Report No 59749 &c

The double bottom tank in No. 3 tank has now been examined internally & the freeboard marks verified.

SUMMARY OF DAMAGE REPAIRS :-

Renewed ...
Removed and Fairied or Repaired ...
Fairied or Repaired in place ...

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items :-

PRESENT CONDITION OF THE

Decks good
Caulking of Decks " "
Waterways " "
Coamings " "
Beams & Fastenings ✓
Outside Plating ✓
Caulking of ditto ✓
Rivets ✓
Breasthooks & Crutches ✓
Transoms ✓
Frames ✓
Reverse Frames ✓
Floors good
Keelsons " "

Stringers ✓
Inner Bottom Plating good
State if Tanks now tested no
Bulkheads ✓
Ceiling good
Cement or Asphalt (State which) " "
Rudder ✓
Windlass " "
Have Pumps now been examined and found efficient? no
Have Sluice Valves now been examined and found efficient? no
Have Watertight Doors now been examined and found efficient? no
Dblg. Plates under Sounding Pipes good

Engine Room Skylights good
Coal Bunkers, Open'gs, Lids, &c. " "
Scuppers " "
Cargo Hatchways " "
Hatches " "
Planking of Wood Vessels " "
Treenails ditto " "
Breasthooks & Stemson ditto " "
Transoms, Pointers, & Crutches ditto " "
Timbers of Frame at openings ditto " "
Ditto ditto at other places ditto " "
Stringers, Clamps & Shelves ditto " "
Salting (State if examined.) ditto " "
Copper, or Y.M. (State if on Felt.) ditto " "
When put on, Month Year

Boats good
Masts, Yards, &c. " "
Condition, how ascertained from Deck
(State if wedges removed no)
Sails ✓
Equipment letter A
Anchors, No. of 5
Cables (State if now ranged) no
" length (on board) size
" Rule length (per Table 22) size
Hawsers & Warps good
Standing & Running Rigging " "

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.98," or "to remain as classed and to have record of survey, 1.98, and the notations of ss No. 1-98 and ptd98, &c."

This vessel now appears to be in good & efficient condition & is eligible in my opinion to remain as classed with record of survey 6.98 and the notation S.S. No. 1-98.

Office Fee (if chargeable) per Scale II., Sec. 27 ... £

Survey Fee (per Section 28) ... £

Special Damage or Repair Fee (if any) (per Sec. 28.) ... £

Travelling Expenses (if chargeable) ... £

Second Surveyor's Fee (if any) ... £

Fees applied for,

18

Received by me,

18

A Campbell Johns

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRI. 1 JUL 1898

Character assigned

100A1
Spar Deck
S.S. No. 1. 97



© 2019

Lloyd's Register
Foundation

LON716-0005