

REPORT of SURVEY for REPAIRS, &c.

Report of Surveying Report 14th Sep 1898 When handed in at Local Office 15th Port of London
 No. in Survey held at London Date, First Survey 9 / Last Survey 12th Sep 1898
 Reg. Book. on the Wood, Iron or Steel 88 "Garth Castle" Master
 TONNAGE:- Built at Glasgow By whom J Elder & Co When 1880 12
 GROSS 3660 Owners D Currie & Co Port belonging to London
 UNDER DEK 3537 Owners' Address
 NET 2350 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock 1 Name of Dock Albert Destined Voyage
 WB=CellDBorDBa feet; uE&B feet; J feet; } Particulars of Classification (which must be inserted
 total capacity tons FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements.)
 N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60036^a Port Low
 Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel's bottom has been examined in dry dock cleaned & coated.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								
PRESENT CONDITION OF THE	Stringers				Engine Room Skylights	good	Boats	good
Decks	Inner Bottom Plating				Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"
Caulking of Decks	State if Tanks now tested				Scuppers	"	Condition, how ascertained	from Dk
Waterways	Bulkheads				Cargo Hatchways	"	(State if wedges removed)	
Coamings	Ceiling				Hatches	"	Sails	✓
Beams & Fastenings	Cement or Asphalt (State which.)				Planking of Wood Vessels	✓	Equipment letter	w
Outside Plating	Rudder	good			Treenails	ditto	Anchors, No. of	6
Caulking of ditto	Windlass	"			Breasthooks & Stenson	ditto	Cables (State if now ranged)	no
Rivets	Have Pumps now been examined and found efficient?	✓			Transoms, Pointers, & Crutches	ditto	" length (on board)	size
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	✓			Timbers of Frame at openings	ditto	" Rule length (per Table 22)	size
Transoms	Have Watertight Doors now been examined and found efficient?	✓			Ditto ditto at other places	ditto	Hawsers & Warps	good
Frames	Have Watertight Doors now been examined and found efficient?	✓			Stringers, Clamps & Shelves	ditto	Standing & Running Rigging	✓
Reverse Frames	Have Watertight Doors now been examined and found efficient?	✓			Salting (State if examined.)	ditto		
Floors	Have Watertight Doors now been examined and found efficient?	✓			Copper, or Y.M. (State if on Felt.)	ditto		
Keelsons	Have Watertight Doors now been examined and found efficient?	✓			When put on, Month	Year		
	Dblng. Plates under Sounding Pipes	✓						

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition and is eligible in my opinion to remain as classed with record of survey 9.98 when the 88 No. 1 has been completed as regards Mch.

Office Fee (if chargeable) per Scale II., Sec. 27	Fees applied for,
Survey Fee (per Section 25)	18
Special Damage or Repair Fee (if any) (per Sec. 25.)	
Travelling Expenses (if chargeable)	18
Second Surveyor's Fee (if any)	
	Received by me,

Committee's Minute
 Character assigned
 FRI, 23 SEP 1898
 100A1
 + 2 Mch 1, 98
 ss No. 1-98
 (on Lon. No. 59775)

Lloyd's Register Foundation
 LON 716-0350