

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 23rd Sep 1898 When handed in at Local Office 18 Port of London

No. in Reg. Book 507 Survey held at London Date, First Survey 9 Last Survey 21st Sep 1898

on the Wood, Iron or Steel 88 "Dunottar Castle" Master

TONNAGE:- Built at Glasgow By whom Fairfield When 1890 8

GROSS 5465 Owners McCurrie & Co Port belonging to London

UNDER DEK 4935 Owners' Address

NET 3069 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock 1 Name of Dock Thames Wh Destined Voyage

WB=CellDBorDBa feet; uE&B feet; J feet; }

total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60039 Port Lon

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER.

* for Special Survey.

Date of last Survey and of Periodical Surveys.

100A1

2nd Sep 98

6.98

88 Lon No 2-97

Society's Freeboard (if assigned) as painted on Ship and now verified }

ft. ins.

Machinery and Boiler Surveys (including date of N.B., if any).

LMC 7.97

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel's bottom has been examined in dry dock, cleaned & coated.

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed	...								
Removed and Faired or Repaired	...								
Faired or Repaired in place	...								

PRESENT CONDITION OF THE		Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps new been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or Y.M. (State if on Fell.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board)	size	Rule length (per Table 22)	size	Hawsers & Warps	Standing & Running Rigging	
Decks	good							good						good																	good		from th	no		at	7	yes	300	2 16	300	2 16	good	
Caulking of Decks	"																																											
Waterways	"																																											
Coamings	"																																											
Beams & Fastenings	✓																																											
Outside Plating	"																																											
Caulking of ditto	"																																											
Rivets	"																																											
Breasthooks & Crutches	✓																																											
Transoms	✓																																											
Frames	✓																																											
Reverse Frames	✓																																											
Floors	✓																																											
Keelsons	✓																																											

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and pEND98, &c."

This vessel now appears to be in good condition and is eligible in my opinion to remain as classed with record of survey 9.98

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for, 18

Received by me, 18

Alampheer Ahmed

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

TUES. 18 OCT 1898

100A1 Spar dk.

8810.98

LON 716-0448