

After stem gland renewed.
Twenty Screw stays renewed in
Donkey Boiler, due to Corrosion.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. ✕ L.M.C. 10.98.

A.C.H.

27.10.98

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation