

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 2nd Mar 99 When handed in at Local Office 15 is 18 Port of London
No. in Reg. Book 1136 Survey held at London Date, First Survey 23rd Feb Last Survey 27th Dec 1899
on the Wood, Iron or Steel S. S. "Strathairny" Master 4 (No. of Visits)

TONNAGE:— Built at Glasgow By whom Burrows & Co When 1894 . 6 MONTH.
GROSS 4142 Owners Burrows & Co Port belonging to Glasgow
UNDER DEK. 3909 Owners' Address -
NET 2704 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? D. 98 Name of Dock Millwall Destined Voyage -
WB=CeILDBoDBa ✓ feet; uE&B - feet; J - feet; }
total capacity - tons. FPT - tons; APT - tons; MT - feet - tons. }

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 868 Port Perth
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. + 100 A 1 + 2. M. C. 6. 94
Date of last Survey and of Periodical Surveys. 12. 97
Machinery and Boiler Surveys (including date of N.B., if any).

Society's Freeboard (if assigned) as painted on Ship and now verified } - ft. - ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Part A. Survey St. 1. In tan repair of 60430.
Hud and bottom examined

in dry dock, at the fore part of St. 1 hold the timbers and ceiling on tank top removed, also cement in girders and a number of rivets in the longitudinal bar of tank side girder cut out & renewed, and two bags of the tank side brackets riveted, a number of shell rivets in way of the inside of the tank renewed, also a few rivets in the floors renewed, the cement in way of this work renewed and ceiling refitted; the inside of St. 1 Tank examined, and the fore and after peak tanks, and St. 1 W. B. tank tested by water pressure. — To complete the survey all the requirements of the rules to be carried out except examination of St. 1 Tank, and the testing of fore & after peak tanks & St. 1 Tank. The owners state that on her return they will get the survey completed. —

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Caulking of Decks			
Waterways			
Coamings			
Beams & Fastenings			
Outside Plating			
Caulking of ditto			
Rivets			
Breasthooks & Crutches			
Transoms			
Frames			
Reverse Frames			
Floors			
Keelsons			
Inner Bottom Plating			
State if Tanks now tested			
Bulkheads			
Ceiling			
Cement or Asphalt (State which.)			
Rudder			
Windlass			
Have Pumps now been examined and found efficient?			
Have Sluice Valves now been examined and found efficient?			
Have Watertight Doors now been examined and found efficient?			
Dblng. Plates under Sounding Pipes			
Coal Bunkers, Open'gs, Lids, &c.			
Scuppers			
Cargo Hatchways			
Hatches			
Planking of Wood Vessels			
Treenails			
Breasthooks & Stemson			
Transoms, Pointers, & Crutches			
Timbers of Frame at openings			
Ditto ditto at other places			
Stringers, Clamps & Shelves			
Salting (State if examined.)			
Copper, or Y.M. (State if on Felt.)			
When put on, Month			
Year			
Masts, Yards, &c.			
Condition, how ascertained			
(State if wedges removed)			
Sails			
Equipment letter			
Anchors, No. of			
Cables (State if now ranged)			
length (on board)			
Rule length (per Table 22)			
Hawsers & Warps			
Standing & Running Rigging			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed without fresh record.

Office Fee (if chargeable) per Scale II., Sec. 27	Survey Fee (per Section 28)	Special Damage or Repair Fee (if any) (per Sec. 28.)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Committee's Minute
£	£	£	£	£	£

Character assigned Deferred for compl. of h.o.
TUES. 7 MAR 1899
TUES. 2 MAY 1899
Surveyor to Lloyd's Register of British & Foreign Shipping.
© 2019 Lloyd's Register Foundation

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?
10,000.—18/10/98.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)
pc. no. 12