

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 14 April 99 When landed in at Local Office London 18 99 Port of London
No. in Survey held at London Date, First Survey 24th Jan Last Survey 30th Jan 18 99
Reg. Book. 89 on the Wood, Iron or Steel SS "Inanda" (No. of Visits) Master H. B. White
TONNAGE: Built at Aburdeen By whom Hall Russell When 1888 6
GROSS 1704 Owners J. J. Rennie & Son Port belonging to Aburdeen
UNDER DE. 1639 Owners' Address
NET 1075 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? both Name of Dock Deptford Green Destined Voyage
WB=CellDBorDBa feet; uE&B feet; feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons.) precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60526 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition
Vessel placed in dry dock, the bottom cleaned examined & recoated. equipment overhauled

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE	Stringers	good	Engine Room Skylights	good	Boats	good		
Decks	Inner Bottom Plating	not seen	Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"		
Caulking of Decks	State if Tanks now tested	no	Scuppers	"	Condition, how ascertained	from deck		
Waterways	Bulkheads	good	Cargo Hatchways	"	(State if wedges removed	no		
Coamings	Ceiling	"	Hatches	"	Sails	good		
Beams & Fastenings	Cement or Asphalt (State which.)	"	Planking of Wood Vessels	"	Equipment letter	2		
Outside Plating	Rudder	good	Treenails	ditto	Anchors, No. of	3B 1 S 2 K		
Caulking of ditto	Windlass	"	Breasthooks & Stemson	ditto	Cables (State if now ranged)	no		
Rivets	Have Pumps now been examined and found efficient?	no	Transoms, Pointers, & Crutches	ditto	" length (on board)	size		
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	no	Timbers of Frame at openings	ditto	" Rule length (per Table 22)	size		
Transoms	Have Watertight Doors now been examined and found efficient?	no	Ditto ditto at other places	ditto	Hawsers & Warps	good		
Reverse Frames	Db'ing. Plates under Sounding Pipes	✓	Stringers, Clamps & Shells	ditto	Standing & Running Rigging	"		
Floors			Salting (State if examined.)	ditto				
Keelsons			Copper, or Y.M. (State if on felt.)	ditto				
			When put on, Month	Year				

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good & efficient condition & eligible, in my opinion, to remain as classed with record of survey 3,99

Office Fee (if chargeable) per Scale II., Sec. 27	£		Fees applied for,	
Survey Fee (per Section 28)	£		18	
Special Damage or Repair Fee (if any) (per Sec. 28.)	£		Received by me,	
Travelling Expenses (if chargeable)	£		18	
Second Surveyor's Fee (if any)	£			

Frank A. Sturgeon
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned

FRI, 7 APL 1899

100A1

Spar dk