

S.S. N: 2. due 6.98. Completion not stated

P.S. to be completed on return.

Screw shaft examined, a new
propeller now fitted.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this
vessel WILL BE eligible for
the record. ~~L.M.C.~~ B.S. 4.99
when the main Boiler Safety
valves have been adjusted
under steam.

Screw shaft and Sea
Connections, Thrust and
Tunnel shafts to be
noted part S.S.

A.C.H.

12.4.99.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation