

Lloyd's Re
Foundation

61149 Lon

Low 61149

And a new rudder pinote fitted.
While the vessel was in dry dock the bottom was cleaned
examined & recoated.

7/11

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation