

Committee's Minute
Character assigned

FRI. 4 AUG 1899

100A

+ 2mc 11, 99
B 37, 99

ps. nd 99

2. no. 3-7, 99

© 2019
FRI. SEP 1899
Lloyd's Re
Foundati
Lon 719-

TUES. 1 AUG 1899

Port of

Continuation of Report No.

61292

dated

on the

S. S. "Maryland"

necessary to have the same drilled.

Now done, from grounding.

Several started rivets found in shell, in way of after peak tank on both sides, all now renewed and bottom cleaned and coated with paint.

Now done from wear and tear.

The main deck found worn and wasted, more than one half now renewed and caulked. The tank top, No 2 section, extending into stoke hold, found wasted thin, now renewed, and after end of this tank doubled; wasted reversed frames and tie plates under boilers efficiently renewed. bunker sides repaired with new plates and angle stiffeners as required. One fractured shell plate on star board quarter renewed. Main topmast, and main top gallant backstays renewed.

J. Skidston.



© 2019

Lloyd's Register
Foundation

LON 719 - 0062 2/2