

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 3-8-99 When handed in at Local Office 3-8-99 Port of London
No. in Reg. Book 29 Survey held at London Date, First Survey 1-8-99 Last Survey 3-8-1899
on the Steamer Steel ss Trainmate Master Hamon

TONNAGE:-
GROSS 5610 Built at Newcastle By whom New Zealand Shipping Co
UNDER DECK 5180 Owners' Address 100 Abchurch Lane, London E.C. 4
NET 3620 Owners' Address 100 Abchurch Lane, London E.C. 4
Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Radock Destined Voyage New Zealand
WB=CellDBorDBa feet 11E&B feet; J feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60837 Port London
Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This steamer was placed in dry dock the bottom examined cleared and repainted.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								
PRESENT CONDITION OF THE	Good							
Decks	Stringers	Inner Bottom Plating	State if Tanks now tested	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches
Caulking of Decks	Bulkheads	Ceiling	Cement or Asphalt (if used)	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches ditto	Timbers of Frame at openings ditto
Waterways	Rudder	Windlass	Have Pumps now been examined and found efficient?	Ditto ditto at other places ditto	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or Y.M. (State if on felt.)	When put on, Month Year
Coamings	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed)	Sails
Beams & Fastenings								Equipment letter
Outside Plating								Anchors, No. of
Caulking of ditto								Cables (State if now ranged)
Rivets								length size
Breasthooks & Crutches								Rule length size (per Table 22)
Transoms								Hawsers & Warps
Frames								Standing & Running Rigging
Reverse Frames								
Floors								
Keelsons								

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This steamer now appears to be in good condition eligible in my opinion to remain as classed with a fresh record of Survey London 8/99

Office Fee (if chargeable) per Scale II., Sec. 27£
Survey Fee (per Section 28)£
Special Damage or Repair Fee (if any) (per Sec. 28.)£
Travelling Expenses (if chargeable)£
Second Surveyor's Fee (if any)£
Fees applied for,18
Received by me,18
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned
100A1 Shelter deck w fbdy
Lloyd's Register Foundation
Low Hia - 0080