

WED. 20 DEC 1899

No. 61737

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 18. When handed in at Local Office 18. Port of London  
 No. in Reg. Book. 526 Survey held at London Date, First Survey Dec 12 Last Survey Dec 16 18 99  
 on the Wood, Iron or Steel S.S. "Dunottar Castle" (No. of Visits 3) Master

TONNAGE:- Built at Glasgow By whom Fairfield & Co. (Lim) When 1890 8  
 GROSS 5465 Owners Castle Mail Packets Co. (Lim) Port belonging to London  
 UNDER DEK. 4005 Owners' Address  
 NET 3069 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Thames (Lim) Destined Voyage

WB=CellDBorDBA feet; u&B feet; f feet; f feet; f  
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years Assigned how expired	Machinery and Boiler Surveys (including date of N.B. if any).
* for Special Survey, Date of last Survey and of Periodical Surveys.		
1-100 A 1	9.99	4.1.10.97
S.S. Ex. 102-97		P.S. 10-99
Spar dk.		

Last Report, No. 61520 Port London

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawseers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel has now been placed in dry dock - the bottom examined, cleaned and recoated. Equipment in good condition.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

## PRESENT CONDITION OF THE

Decks	gnd	Stringers	gnd	Engine Room Skylights	gnd	Boats	gnd
Caulking of Decks	"	Inner Bottom Plating	—	Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"
Waterways	"	State of Tanks now tested	—	Scuppers	"	Condition, how ascertained	from deck
Coamings	"	Bulkheads	gnd	Cargo Hatchways	"	(State if wedges removed)	
Beams & Fastenings	"	Ceiling	"	Hatches	"	Sails	gnd
Outside Plating	"	Cement or Asphalt (State which.)	mt. elem	Planking of Wood Vessels	"	Equipment letter	at
Caulking of ditto	"	Rudder	gnd	Treenails ditto	"	Anchors, No. of	
Rivets	"	Windlass	"	Breasthooks & Stimson ditto	"	Cables (State if now ranged)	gnd
Breasthooks & Crutches	mt. elem	Have Pumps now been examined and found efficient?	—	Transoms, Pointers, & Crutches ditto	"	" length (on board)	gnd
Transoms	"	Have Sluice Valves now been examined and found efficient?	—	Timbers of Frame at openings ditto	"	" Rule length (per Table 22)	gnd
Frames	gnd	Have Watertight Doors now been examined and found efficient?	—	Ditto ditto at other places ditto	"	Hawseers & Warps	gnd
Reverse Frames	"	Have Watertight Doors now been examined and found efficient?	—	Stringers, Clamps & Shells ditto	"	Standing & Running Rigging	gnd
Floors	mt. elem	Have Watertight Doors now been examined and found efficient?	—	Salting (State if examined.) ditto	"		
Keelsons	gnd	Have Watertight Doors now been examined and found efficient?	—	Copper, or Y.M. (State if on felt.) ditto	"		
		Dbng. Plates under Sounding Pipes	—	When put on, Month	Year		

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and pnd 98, &c."

This vessel appears to be in good condition & is eligible in my opinion to remain as classed with record of survey 12.99

Office Fee (if chargeable) per Scale II, Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 25.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

18.

Received by me,

18.

Committee's Minute

Character assigned

22 DEC 1899

100A1

Spar dk.

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

LON 720-0221