

1
Mr. Davey's Report on the repairs to
the S.S. "Lydian Monarch".

It is submitted that the repairs to this
vessel appear to have been conducted in a
satisfactory manner, and the vessel appears to
be eligible to remain as classed, and marked S.S. 401-83
subject to the one length of chain now repaired being re-tested on vessel's return.

Experience has now shown that in cases
where ^{steel} plates have been exposed to local heating
as in this, if they be properly annealed they
can be brought back to their original condition
and freed from the injurious effects of the local
or partial heating.

B.M.

J.H. B.
2/6/86

G.C. 3/6/86.



© 2021

Lloyd's Register
Foundation

LON723-0125