

P

Rye.
July 30/80

Search.

Pioneer Boiler

Yours of the 27th I have

I am surprised at the report of your Surveyor that "leakages are not of a serious character & in his opinion they are due to unequal expansion" & I must ask if the leakages round the front manholes are due to unequal expansion.

if the leakage round front bottom seam & into which a trowel could be inserted


one inch are due to this cause & whether a crack in combustion chamber & which your Surveyor does not report, are also due to same cause.

When these questions are satisfactorily answered I shall be pleased to shut the charges.

This is a most serious matter to the owners of the vessel & must be seen into further.

Yrs faithfully
A. Reene

B. Waymouth Esq



Lloyd's Register
Foundation

From Mr. Pitman's special survey of this Boilers
there does not appear to be any ground for
complaint, it is submitted that a full
copy of Mr. Pitman's report be sent to
the owner

MP
2-8-88

LOW

21/7/88
Mr Parker &
Mr. Pitman
copy



© 2021

Lloyd's Register
Foundation