

4
Case of the Steel Screw Steamer "Echuca",
No 108 in the Register Book, built at
Middlebro' in 1889, and classes 100 A 1

Mr Lund, the owner of this vessel,
recently called here and complained of
symptoms of straining that has been
observed in her. The vessel being in
graving dock in London, Mr Cornish was
instructed to survey her, and on the
receipt of an unsatisfactory report
from him, Mr Williams, Surveyor at
Hartlepool, under whose survey the
vessel was built, was directed to come
to London, and to join Mr Cornish in a
further survey. The symptoms of
straining observed at this further
survey, are referred to in the appended
letter, dated 3rd July, from Mr Williams.

R. W.

25/7/89



© 2021

Lloyd's Register
Foundation

LON 124 - 00 58