

Surveyors Statement of Chain Cables on board.
of the "Rangitiki"

135 fathoms from Ottolina 2"
45 " " Blackwall. $1\frac{13}{16}$.
90 " of her own chain.
270 fathoms. as required by Rule.

New Zealand Shipping Co. Statement.

130 fathoms from Ottolina $1\frac{11}{16}$ to 2"
120 " " " " "
45 " " Blackwall $1\frac{3}{16}$.
90. " of her own chain.
385 fathoms.

Chain Cables reported to be on board by
Messrs. Campbell & Todd.

Port-Side	120 fathoms	{ 90 fathoms $1\frac{10}{16}$
		{ 30 " $1\frac{12}{16}$
Starboard-Side	90. " $1\frac{14}{16}$.	
" "	85 " $1\frac{11}{16}$.	
	✓ 50 " $1\frac{7}{16}$.	
	<u>345</u> fathoms.	

© 2021

Lloyd's Register
Foundation

LON 725-0245