

Copy

Lloyd's Register of British and Foreign Shipping.

Lyttelton, N.Z. Dec 18th

1890

J. Gibbs Esq

Sect. N.Z. S.C.

Sir.

I examined some 50 fth of chain cable ex "Blackwall" & found it where rust was beaten off links to be $1\frac{1}{16}$ & in my opinion sufficient for Temporary Purposes for your vessel the "Rangitiki" of course it is understood this length is to be replaced with proper tested chain on vessel's arrival home.

Yours faithfully
Robert Leitch
Secy. N.Z. S.C.



© 2021

Lloyd's Register
Foundation

LON 725-0258