

Sent to Chief Surveyors

17/4/92

Received from Chief Surveyors

VESSEL'S NAME

Rio Tejo

Report

London No. 53015

For the remarks of the CHIEF SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

S.S. No. 2

due

March 1891 B.S. due

It is submitted that M<sup>r</sup> LeLaidier should be requested to inform the Bureau that before the chain cable in question can be accepted, it must be tested as required by Table 22 at a Towing Establishment recognised by the Committee and the test certificate produced and verified by a Surveyor to this Society when the cable has been placed on board the vessel.

Lr to Nav: 2015/92



© 2021  
Lloyd's Register

18.5.92.  
Foundation