

Sent to Chief Surveyors

28/5/92

Received from Chief Surveyors

VESSEL'S NAME

Rio Tejo

Report Lon

No. 53015

For the remarks of the CHIEF SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

S.S. No.

2

due

3 91

B.S. date

It is submitted it should be pointed out to the Owners that the test applied to the length of chain cable in question was less than that required by Table 22 of the Rules for a chain of its size and that while there is no doubt as to the integrity of officials named the Committee can only accept for vessels classed in the Society's Register Book, anchors and chains which are tested in accordance with the Rules at one of the Proving establishments recognised by the Committee.

The names of these Proving Houses are given in Table 22, a copy of which should be sent for the Owners information, and they should be requested to arrange for the length of chain cable to be tested at a recognised Proving House at the earliest opportunity, and afford an opportunity for one of the Society's Surveyors to inspect the same and compare it with the test certificate when placed on board the vessel.

Lr to Owners:— 30/5/92.