

COPY.

S.

11th November, 1892.

Dear Sirs,

With reference to the classification in this Society's Register Book of the Steamer "MASSACHUSETTS", I am directed to acquaint you that it appears from a report received from the Society's Surveyor at New York that some rivets in the shell plating on the starboard side were found to be leaking, and other rivets showing signs of straining.. Temporary repairs were effected to enable the vessel to return to this port, where it is understood she will be docked and have the necessary permanent repairs carried out.

I shall therefore feel obliged if you will kindly let me know when the steamer will be ready for inspection.

I am,

Dear Sirs,

Yours faithfully,

MP.
Messrs. Williams, Torrey & Field,
108, Fenchurch St., E.C.



© 2021
Secretary.

Lloyd's Register
Foundation