

P. S. "John Pender"
Eastern Telegraph Co. Limited.

To complete the Special Survey on the Machinery

- The Main and Donkey Boiler Safety valves ^{require} to be
adjusted under steam.
(5) The propeller shaft (if deemed necessary by the
Surveyor) propeller, stern bush, Sea connections and
fastenings to be examined.

M. Salmon
15/11/95

To Owners
20/11/95.

checked at
13/1/96
W. L. L.



© 2021

Lloyd's Register
Foundation

LON729-0365