

Sent to Chief Surveyor

12.10.96

Received from Chief Surveyor

VESSEL'S NAME

Ship 'Indian Empire' Report

No.

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Repair, S. S. No 1

When due 4.95, deferred

This vessel was partly dismantled. New masts and spars were made at Liverpool under the inspection of the Society's Surveyors, and sent out to Callao. They have been fitted in the vessel together with new rigging, and certificates have now been received from two nautical men appointed by Lloyd's Agent at Callao to inspect the same, in accordance with the Committee's decision of the 8th. February last.

The masts, spars and rigging are stated to have been satisfactorily fitted, and are, together with the vessel and equipment, reported to be in good condition.

A telegram was received from Lloyd's Agent at Callao to this effect on the 8th. September, ~~and the~~, and the Committee thereupon decided to re-instate the vessel's class in the Register Book on the understanding that she be submitted to the examination of the Society's Surveyors, and the S.S.No.1 (due 4, 95) held on her return home, and if she proceeded to San Francisco or any other port at which the Society has a Surveyor stationed, that the masts, spars and rigging should be submitted to examination.

The vessel is now proceeding to San Francisco, and the Surveyor at that port has been requested to place himself in communication with the Master on the vessel's arrival, with a view to the masts, spars, rigging, and repairs being examined.

It is submitted that action be deferred until receipt of a report from the San Francisco Surveyor.

Let to Lloyd's agent: 14.10.96.
(14.10.96)

© 2021 Lloyd's Register Foundation
13.10.96

LO730-0153