

Received by Chief Surveyor 15.3.97

Received from Chief Surveyor _____

VESSEL'S NAME Wood. Steamer Emerald Report Lon No. 58606

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Re-installment of class & Continuation Survey
No 2.

This vessel was originally classed 9A-, which was withdrawn at the Owners' request in 1894.

The Continuation Survey No.2, per section 54 of the Wood Rules has now been held, and the following repairs due to wear and tear effected;- One beam, coamings, framing and deck in way of Boiler space, renewed, keelson under boilers repaired and minor repairs effected.

It is submitted the vessel appears eligible to have her class 9A- reinstated in the Register Book, with record of survey 3.97.Lyn, and to be continued on the A character for 6 years from 2.98, that is at the expiration of her original class.

9A- Re-instated in R.B
"For Listing Purposes"
3-97 Lyn. E.B

And to be Classed

Cont 6A-

from 2.98 Lyn

At expiration of original class



© 2021

E.B
Lloyd's Register
Foundation
15.3.97

LAN731-0029