

Received by Chief Surveyor

1-6-97

Received from Chief Surveyor

VESSEL'S NAME

S.S. "Agnes"

Report

Lon

No. 58856

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S.S. No. 2 in damage

in 10.95,

The S.S.No.2 due 1,95 ~~was~~ held at Danzig with the exception of some repairs to the floors under the boilers and the bunker bulkheads, has now been completed and the following repairs done:- 6 floors under the boilers renewed, and double reverse bars fitted to others. The lower part of stokehold bulkhead, the bunker bulkheads and lower deck stringer in bunkers repaired, the main and bridge decks overhauled and minor repairs effected,

Some damage through ice reported in February 1897 as temporarily repaired has been permanently repaired as follows:- 3 plates and some keel rivets renewed and minor repairs.

It is submitted the vessel appears worthy to remain classed ^{A1} with record of survey 5,97 Lon. and the notation S.S.Dnz. No.2,95 as recommended.

A1

5-97 Lon

S.S. Dnz No 2-95



© 2021

dam
1/6/97

Lloyd's Register
Foundation

LONT31-0116