

Received by Chief Surveyor

11-5-98

Received from Chief Surveyor

VESSEL'S NAME

*Insurg Altata*

Report

*Ingt*

No.

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*S.S. No. 2*

*h<sup>o</sup> 1 due 10 94  
h<sup>o</sup> 2 due 10 98*

A report has been received from a Surveyor nominated by Lloyd's Agent at Mazatlan, from which it appears that all the requirements of the S.S.No.2 have been complied with, but he states that the keel plates require to be renewed from middle of vessel to stern frame, and that the riveting <sup>in same</sup> is defective.

No repairs have yet been effected, but a letter has <sup>now</sup> been received from the Owners in London, who state their Manager at Mazatlan has asked for some keel plates to be sent to him.

It is submitted the Owners be requested to state what arrangements they propose to make with reference to the required repairs in order to render the vessel eligible to retain her class.



*© 2016*

*12/5/98*

Lloyd's Register  
Foundation

LON731-0279