

Received by Chief Surveyor 16/11/98

Received from Chief Surveyor

2

VESSEL'S NAME Iron BK. "Peri" Report Lon. No. 60440

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

2nd S.S. No. 3

The S.S. 2nd No. 3 has now been held, and the following repairs done (due to wear & tear):—

Bailij, cement, pumps, pillars, steering gear & rigging repaired & minor repairs. Doublings fitted under sidelights. Rudder relushed. 4 topmasts & 2 yards renewed & minor repairs & renewals to spars & rigging.

The plating has been drilled with satisfactory results.

It is submitted the vessel is worthy to remain classed

*A1

with record of Survey 11/98 and notation of S.S. Lon

2nd N° 3- 11.98 as recommended.

*A1

11/98. Lon.

S.S. Lon. 2nd N° 3- 11.98.



© 2021

16/11/98
Lloyd's Register
Foundation

LON732-0104