

As this vessel class was withdrawn in 1899 at which time she was in an unsatisfactory condition and as the vessel has not since had the Society's classification.

It is submitted the owners should be informed that before she can be re-instated upon her original classification the vessel should be surveyed and <sup>examined</sup> reported upon by one of the Society's exclusive surveyors - say at Genoa or at Constantinople. They should further be informed that the Naples Surveyor is not an exclusive surveyor to the Society.

J.P.L. 23/6/05

J.L.M.




© 2021

Lloyd's Register  
Foundation

LON732-0180





© 2021

Lloyd's Register  
Foundation