


S. L. Pot the Painter

The report on machinery of this vessel is incomplete  
It is submitted that it be returned to the Surveyor  
to be completely filled up in the parts marked  
in red & that with reference to the Spare Gear he  
should be asked to state why he has recorded that  
none is required

S. L. M. 26/5/92



© 2019

Lloyd's Register  
Foundation

LTH 562-0081

The Topsides & Sneeer-strakes