

Gross Tonnage 184.0
 Less Crew Space 20.
 Less ab/Eng
 Tonn.

1st Number 4126
 Length on deck from after part of stem to fore part of 108.

Owners Muirheads Trawlers (Kin)

F.E.

Received by Chief Surveyor 24.10.98

Received from Chief Surveyor

EL'S NAME *St. Steam Trawler "Simplon"* Report *Lth.* No. *8885*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>7/16" in lieu of 7/8"</i>	<i>Not required</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Ordinary, 5/16" thick in lieu of 5/20"</i> (viz., ordinary, deep, zed, channel or bulb-angle). <i>Steel not required.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100 A1 ("Steel") Steam Trawler* as recommended.

*+ 100 A1 ("Steel")
 Steam Trawler
 1 DR.
 BK 7 1/2" 3 BH Cen. A & C.P.*

*C. H. J.
 24/10/98*



© 2019
 Lloyd's Register
 Foundation

LTH 568-0024

Actual	Inches per Rule Or as App	Inches per Rule Or as App
	7 1/2	
	6	
	3	
	2 1/2	
	6	3
	5	4
	5	4
	23	
	3	3
	7	
	3	

Hold	Quarter, 'tween Dks., in Hold						

Forecastle Deck
 Angle on ditto.....
 m. Plater