

Chief Surveyor 13.10.96

Received from Chief Surveyor

NAME *Shce & Son S.S. Barely "Ready"* Report Sub. No. 1895

Remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

vey

First entry.

It is submitted that before this case receives the consideration of the Committee, this report should be referred to the London Surveyors, and they should be requested to see that the openings round the E & B openings in the deck are satisfactorily fitted up when the machinery has been fitted, and to report upon same for the information of the Committee.

London Surveyors.

C.H.F.
28/10/96

The Surveyor (Mr. Wilson) should be requested to state the name of the Manufacturers of the Engine in the construction of the Vessel, as this is not stated in his report.

Sub. 20.10.96.



© 2019

C.H.F.
28/10/96
Hoyt's Register
Foundation

MPB755-0151

23 OCT. 1896