

L. B. "Peerless"

Submitted the Middleboro' Surveyors
be requested by wire to state whether
the thicknesses of C and D strakes of
the outside plating should not be
 $\frac{11}{20}$ " and $\frac{12}{20}$ " instead of $\frac{10}{20}$ " and $\frac{11}{20}$ " as
noted on the first entry report.

L.B.

3. 11. 98



© 2020

Lloyd's Register
Foundation

MD8760-0040