

Steel S. "Speke"

Mil. 1<sup>st</sup> Entry Sept. 1800

It is submitted that before this case can be put forward for the Committee's consideration, the Report should be returned and the Surveyor at Milford should be requested to state thereon whether the rivets in the landing edges of the shell plating are 4" centres as marked, or about  $3\frac{3}{8}$ " as required by the Rules.

The name of the makers and the particulars of Tests as per certificates, which it is presumed were supplied with the Steel wire Rammers, should be given, and Mr. Seccombe should sign his name in the space reserved for the purpose at the end of the Report.

Lr. to Mr. Seccombe

13.3.91

Rept recd



© 2021

Lloyd's Register  
Foundation

*Handwritten signature*  
13.3.91