

Report - Mon.

21st April 1891

Herbert M. Rogers & John H Heck

3

the owner, examine on the
 1st inst & following day, the Iron
 Screw Steamer, "I. LANDAFF," 243 tons
 register, while lying in the Old Dry
 Dock, for the purpose of ascertaining
 the damage stated to have been
 sustained through striking the Quay
 at Hayle on the 11th Jan^y last.
 For full particulars see Entry in
 Log-book.

Found,

The Sheerstrake & one forecable
 plate on the port bow, fractured, long
 feet of moulding destroyed, chafing rim of
 port hawse-pipe broken & caulking of deck
 in way of damage started.

Recommended,

the
 two broken plates to be renewed, the
 damaged moulding to be renewed,
 the

Llandaff

2

the chafing pipe on ring on port
kivore-pipe to be renewed & the
caulking of deck (where) started to be
renewed; good so as to put the
vessel into the same efficient
condition as before.

See L-1-

John H. Heck.

Herbert M. Rogers

The above Damage on the
1st inst. a following day the following
Steamer "LLANDAFF" was lying
apiece, while lying in the old dry
dock, for the purpose of ascertaining
the damage stated to have been
sustained through striking the quay
at Hays on the 11th Jan^y last.
For full particulars see Entry in
Log book.

The Damage is as follows:
Plate on the port bow fractured, being
part of building destroyed; chafing ring of
kivore-pipe broken & caulking of floor
of damage started.

Recommended.



© 2021

Lloyd's Register
Foundation