

Newcastle No 287

This is to certify that we repaired the Brig  
Hylton. At John G. Reay's order in Dec<sup>r</sup> 1831.

New Keel. 7 Floor Timbers.

21 First Puttocks. Nelson.

One Hold Beam, part New Knees.

The Hold Beam bolts strighted out & replaced  
where required.

Lower Hold new ceiled, and about 2000 Runners  
replaced, also thoroughly Caulked.

Witness our Hands at South Shields this 17<sup>th</sup> July 1835

C. Young & Sons



© 2018

Lloyd's Register  
Foundation