

"Brig
Harebell"

Extract from Mr. Martin's Report
dated June, 1864.

Recommended a defective plank of Hold
Beam Spiritetting to be replaced - the owner
promised to adopt the recommendation.

NWC776-0138

The Second Foothooks of English Oak

The Third Foothooks and Top Timbers of English

The Shifts of the First and Second Foothooks are not less than 3 ft. 10

N. B. When less than prescribed by the