

2nd. On the plating during the process of riveting
3rd. When the beams were in and fastened,)

NWL785-0023

10.23 Oct 2.4.7.12.17.18.21.24.26.31. Nov. 3.6
9.13 20 23 27 Dec 7 10 13 16

REPORT, No. *16728*
ON THE *Malek*

FROM

Newcastle

DATE

12/4/83

REMARKS OF THE CHIEF SURVEYOR.

*It is submitted that this vessel
appears worthy the favorable consideration
of the Committee to be classed 100 A.1. Spar
as recommended.*

12th Iron Spar OK,

3 Hiers Beams

South Bottom particulars appended.

13/4/83

*Lloyd's Register
Foundation*