

1st. On the several parts of the frame, when in place, and before the plating was wrought.

1883 Aug 16. September 2/

NWC 789-0040

REPORT, No.

17294

FROM

Newcastle

DATE

15/1/84

ON THE

John Grafton

REMARKS OF THE CHIEF SURVEYOR.

It is submitted that this vessel merits the favorable consideration of the Committee to be classed 100 A.1 as recommended, provided the stream chain has been tested as required by the Rules. (no test being recorded on the Report)

1st (Iron)

Double Bottom for 2 & Fore Peak Tank 17/1/84

frame & Stem fraying Report now returned

Lloyd's Register
Foundation