


No. 2284

(Received in London Office



TESTS OF BOILER STEEL.

Date first visit ☒ last visit ☒ No. of Visits ☒

The ~~16 test plates~~ specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests to a shearing from each plate, with satisfactory results.

[illegible]

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee £ : :

Expenses £ : :

£ : :

To be paid by Messrs. J. Colville & Sons

Surveyor, Lloyd's Register,

Glasgow
9/2/85

S.S. "Buccaneer"
Nwc. Report No. 18754



© 2021

Lloyd's Register
Foundation