


No. 5904

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 5 Steel plate manufactured by Messrs S. Colville & Co of Motherwell for Boiler No. 970 to be constructed by Messrs Blair & Co of Stockton-on-Tees for ✓

Date first visit 29/11/87 last visit 1/12/87 No. of visits ✓

The ✓ specified in the accompanying copy of Advice Notes were rolled from ✓ charges. The tensile test has been applied to ✓ samples as set forth below, and the temper and bending tests applied to each plate with good results


When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	6-11" R x 55 3/4" x 1 3/16"	749		7768	1.2	1.1	1.32	37.5	28.4	28.0	

29
5/12/87

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by



© 2021
 K. A. and
 Surveyor, Lloyd's Register,
 Glasgow

1/12/87