

No. 6147

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 25 Steel plates manufactured by Messrs Edwille & Sons of Motherwell for Boiler No. 984 to be constructed by Messrs Blair & Co of Stockton-on-Tees for

Date first visit 28/2/88 last visit 4/1/88 No. of visits 2

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 3 samples as set forth below, and the temper and bending tests applied to each plate with good results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	T. ns.	Tons.	%	
	5-10 1/2 x 4 1/4 x 7/8	Steak		5765	.9	1.07	1.683	49.56	29.4	29.5	
	15-3 3/4 x 5 1/2 x 1	P265		8801	1.05	1.2	1.26	34.7	27.5	25.5	
	21-5 1/2 x 5 1/4 x 1 1/8	P265		7410	1.37	1.25	1.887	44.5	28.0	25.0	

D.P.
9/1/88

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by



© 2021
 Lloyd's Register
 Surveyors Lloyd's Register
 Glasgow
 4/1/88