



No. 1119

(Received at London Office)

TESTS OF BOILER STEEL.

Tests of Steel Plates manufactured by Heardale Iron Coal Coy of Spennymoor
 for Boiler No. 984 to be constructed by Blain & Co of Stockton
 for Shipping 167 No 154

Date first visit 4th Jan'y '88 last visit _____ No. of visits _____

The Plates specified in the accompanying copy of Advice Notes were rolled from
 _____ charges. The tensile test has been applied to _____ samples as set forth below,
 and the temper and bending tests were good.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<u>Boiler Plate</u>		<u>4684</u>	<u>a</u>	<u>.571</u>	<u>1.48</u>	<u>.800</u>	<u>22.98</u>	<u>28.4</u>	<u>24</u>	<u>17.1.88</u>

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by _____

© 2021

Wm. R. Austin
 Surveyor, Lloyd's Register,
Great North Street